## Storey County Building Department PO BOX 526 - VIRGINIA CITY, NV 89440 - (702) 847-0966

Permit #:

8417

Requested:

9/23/08

## CODE COMPLIANCE INSPECTION REPORT

9/24/08 3:25 p.m.

Inspection Date/Time

Ready:

9/24/08

Mileage:52165

Shannon Gardner, Inspector

Site Address: 370 Panamint APN #003-431-18		Area: HR	Lot / Blk 37
Owner: Taormina, Tom	Contractor: OB		
INSPECTION(s) REQUESTED:			
1. Footing Stemwall Ready to Pour Concrete - Forms in, UFER Ground, Reinf. Stl. In-Place			
2.   Floor Joists - Mud Sill, J-Bolts and Blocking In as Required; Rough Plumbing Installed			
3. Roof Sheet Nailing - Nail Spacing and Sheathing Spacing			
4. Tramed Complete - Plumbing thru roof, Elect. Boxes in, Wire Pulled, Heating, Gas Piping, Roof Shingled, Siding On, Dry In			
5. Insulation a. Batts b. Blown - CERTIFICATION Required			
6. Sheet Rock Nailing			
7. Ready to Occupy – a. Sheetrock Finished b. Plumbing c. Electrical d. Heating and e. Grading All Completed			
☐ Electrical       ☐ Electric Service Connections       ☐ Fuel Burning Stove         ☐ Mechanical       ☐ Excavation & Grading       ☐ Demolition         ☐ Plumbing       ☐ Foundation       ☐ Exterior Gas			ove
~ REINSPECTIONS ~  NOTE: It shall be the duty of the person doing the work authorized by a permit to notify the Building Department that such work is ready for Inspection and to provide access to and means for Proper Inspection of such work. A re-inspection fee will be assessed for each inspection when such Portion of work for which Inspection is called is not complete or when corrections called for are not made.			
Condition of Construction at this Inspection:  A. Meets ALL Requirements for this INSPECTION  B. Substitutions or Deviations  D. Non-Compliance – Builder Will Comply Without Delay  D. Non-Compliance – Builder Does NOT Intend to Comply  E. Dwelling is habitable, however the following corrections MUST be completed by			
Tower appears to be no more than 40' in height, OK Anchors and all components are within the set-backs required for structures, OK Engineering report has been delivered to Building Dept.  PASS, No further inspection required.  CERTIFICATION – I certify that I have inspected the above property and have reported herein all conditions observed at this time and			

Rev 01-06-04